

6: District Facilities Assessment

Site Recommendations for Crawford High Educational Complex



SITE DATA	CRAWFORD HS	334
Site Net Acreage:	26.9	
Total Permanent Building Sq. Footage:	176,555	
Total Quantity of Classrooms:	85	
Quantity of Permanent Classrooms	70	
Number of Permanent Buildings	14	
School Program Capacity	1977	
Current Enrollment - 2007-08	1514	
Projected Enrollment - 2016-17:	1434	
Student to Acre Ratio:	56	
Quantity of Portable Classrooms	15	
% of Total Classrooms in Portables	18%	
Quantity of Portable Buildings on Site	21	
Quantity of Undersized Classrooms	15	
% of Undersized Classrooms	18%	
API Rating (2007 Base Statewide Rank)	N/A	
Quantity of buildings over 50 years	12	
Age of Building-% over 50 years	86%	
FCA Rating	Fair	
Climate Control	III	
ADA Report	Poor	
Delta from Capacity	463	

Site Findings:

- This school campus is made up of multiple Small Learning Communities and therefore have multiple API scores
- The campus is not overcrowded & buildings appear to be in relatively good condition
- Site has 21 Portables not certified. 8 portables are over 40 years old
- Crawford High has been transformed into 4 small schools within the campus, each with its own career theme
- New library addition & science lab upgrades were completed as part of the Prop MM work
- Many restrooms on site still need to be upgraded for ADA compliance
- Storm water management is a problem in several areas on the site
- Fire Restoration has taken place in several classrooms in building 800
- Only minor updates were completed as part of Prop MM
- Most of the standard spaces for a high school are included on this campus
- There is poor ventilation in classrooms, cafeteria, and most restrooms
- Many of the classroom & office spaces are subjected to very high temperatures
- The site representatives indicated a need for improvement for the dining and food service facility

Site Recommendations:

- The campus needs minor site work to correct drainage problems
- Exterior painting, landscaping and new signage is needed to improve the “curb appeal” of the school in the neighborhood
- Appropriate shade structures are needed in several areas of the campus



6: District Facilities Assessment

including the athletic fields

- Both staff and student restrooms need to be upgraded for ADA compliance and improved ventilation
- Consider modifying the cafeteria with a different window or large door configuration for better ventilation of this space

Input From Site Surveys:

- Appearance improvements and exterior painting of site requested
- Removal of excess of unnecessary electrical wiring requested
- Door between Room 101 and 110 requested
- Replacing portables with permanent structures requested
- Self-closing gates for increased security requested
- Site has no central PA system, highest priority for site
- Food service upgrades requested
- No-cut fencing requested throughout site to match back of school

Input from Cluster Meetings:

- Request upgraded wiring and electrical output for rooms with heavy technology
- Auditorium needs acoustical and lighting upgrades
- Request better control of heat/boiler for buildings
- Report problem with skaters during weekend and after hours
- Fields reportedly are not well maintained, putting students at risk for injuries
- Request upgrade of faculty bathrooms
- Request storage for golf carts
- Request ceiling-mounted video projectors, district-wide student email, sound system for classroom instruction
- Request computer lab, weight room, work room, student support room, student store, staff area
- Request artificial turf, additional locker rooms, team rooms, training rooms
- Would like film room and study hall room
- Benches and display boards reportedly need to be replaced
- Update computers in classrooms and library
- Request dedicated space for language labs
- Request security cameras throughout campus
- Upgrade exterior/interior lighting