



6: District Facilities Assessment

Site Data Evaluation for Holmes Elementary School

SITE DATA	HOLMES ES	147
Site Net Acreage:	9	
Total Permanent Building Sq. Footage:	29,060	
Total Quantity of Classrooms:	25	
Quantity of Permanent Classrooms	14	
Number of Permanent Buildings	6	
School Program Capacity	470	
Current Enrollment - 2007-08	442	
Projected Enrollment - 2016-17:	415	
Student to Acre Ratio:	49	
Quantity of Portable Classrooms	11	
% of Total Classrooms in Portables	44%	
Quantity of Portable Buildings on Site	11	
Quantity of Undersized Classrooms	0	
% of Undersized Classrooms	0%	
API Rating (2007 Base Statewide Rank)	9	
Quantity of buildings over 50 years	0	
Age of Building-% over 50 years	0%	
FCA Rating	Poor	
Climate Control	II	
ADA Report	Poor	
Delta from Capacity	28	

Site Findings:

- The school is deficient 789 sq. ft. of administration & instructional support space to meet district standards
- 11 portables are not certified. 6 portables are over 40 years old

Input from Site Survey:

- Wireless network needed campus-wide to support current technology
- Permanent kindergarten classrooms with restrooms needed
- Athletic field and track reported to need new turf
- Additional lab rooms needed to support art, music and science programs
- New HVAC requested in all buildings and classrooms
- Campus-wide PA system needed
- Video surveillance requested to deter vandalism and security concerns
- New dining facilities and equipment needed to accommodate student population
- Frequent plumbing problems reported due to dilapidated plumbing
- New student drop-off needed due to safety concerns and vehicular congestion
- Landscaping, irrigation and campus beautification reported as needed
- Some portables are not wheelchair accessible
- Inadequate exterior lighting reported campus-wide
- Inadequate restrooms to support faculty and students
- Exterior furniture requested
- Joint-use field program requested



6: District Facilities Assessment

Input from Cluster Meetings:

- Request mounted document camera, audio equipment for teachers, and smartboards
- Request additional ceiling fans
- Request replacement of lunch tables and “cafetorium” partition
- Blacktop is reportedly uneven—request resurfacing
- Shade structure needed in kindergarten area
- Request science lab and art class space
- Entire school needs to be painted (interior and exterior)
- Request reading area
- Request additional kitchen facilities
- Request additional campus lighting, motion sensor lighting, alarms, fencing

