

6: District Facilities Assessment

Site Data Evaluation for Morse High School

| SITE DATA | MORSE HS | 352 |
|--|----------|-----|
| Site Net Acreage: | 40 | |
| Total Permanent Building Sq. Footage: | 197,380 | |
| Total Quantity of Classrooms: | 125 | |
| Quantity of Permanent Classrooms | 82 | |
| Number of Permanent Buildings | 21 | |
| School Program Capacity | 3087 | |
| Current Enrollment - 2007-08 | 2714 | |
| Projected Enrollment - 2016-17: | 2258 | |
| Student to Acre Ratio: | 68 | |
| Quantity of Portable Classrooms | 43 | |
| % of Total Classrooms in Portables | 34% | |
| Quantity of Portable Buildings on Site | 46 | |
| Quantity of Undersized Classrooms | 1 | |
| % of Undersized Classrooms | 1% | |
| API Rating (2007 Base Statewide Rank) | 3 | |
| Quantity of buildings over 50 years | 0 | |
| Age of Building-% over 50 years | 0% | |
| FCA Rating | Fair | |
| Climate Control | III | |
| ADA Report | Poor | |
| Delta from Capacity | 373 | |

Site Findings:

46 portables are not certified; 22 portables are over 40 years old

Input from Site Survey:

- Upgrade to electrical panel (room 301) needed because capacity is not able to sustain existing technology requirements
- Additional cooling for network server room (adj. room 801) is needed to sustain existing equipment
- Administration building and some classrooms reported not having HVAC and fans/cooling system
- Upgrade perimeter gates due to weekly vandalism and increase campus security
- Some exterior lamps (athletic field lamps) reported as non-operational
- Poor irrigation and holes in athletic fields reported and need to be repaired

Input from Cluster Meetings:

- Request PA system and sound system in auditorium
- Electrical problems site-wide reported
- Request ceiling-mounted projectors
- Request security cameras throughout campus
- Report that restrooms need to be repaired/upgraded
- Request degumming project
- Painting over graffiti requested
- Need bleachers and turf for football field
- Landscaping needed





6: District Facilities Assessment

- Drainage is reportedly a problem at bus stop and between 800 building and north auditorium
- Potential irrigation needs reported

