



Site Recommendations for Iftin Charter School at Jackson









| SITE DATA | IFTIN @ JACKSON | 74 |
|--|-----------------|----|
| Site Net Acreage: | 3.2 | |
| Total Permanent Building Sq. Footage: | 41,720 | |
| Total Quantity of Classrooms: | 42 | |
| Quantity of Permanent Classrooms | 22 | |
| Number of Permanent Buildings | 7 | |
| School Program Capacity | N.A. | |
| Current Enrollment - 2007-08 | 143 | |
| Projected Enrollment - 2016-17: | 144 | |
| Student to Acre Ratio: | 45 | |
| Quantity of Portable Classrooms | 20 | |
| % of Total Classrooms in Portables | 48% | |
| Quantity of Portable Buildings on Site | 23 | |
| Quantity of Undersized Classrooms | 0 | |
| % of Undersized Classrooms | 0% | |
| API Rating (2007 Base Statewide Rank) | 1 * | |
| Quantity of buildings over 50 years | 5 | |
| Age of Building-% over 50 years | 71% | |
| FCA Rating | Fair | |
| Climate Control | III | |
| ADA Report | Poor | |
| Delta from Capacity | N.A. | |

Site Findings:

- The school is deficient 408 sq. ft. of administration & instructional support space to meet district standards
- 21 Portables are not certified, 15 of which are over 40 years old
- Site location & layout present safety/security issues
- Limited parking & play area on site
- Site & buildings are in poor condition
- 6 Kindergartens do not include restrooms in classrooms
- 2 buildings on site were reported to require major structural repair
- Classrooms have acoustical challenges due to site location & existing HVAC

Site Recommendations:

systems

- Investigate proposed grade configuration and projected enrollment for the school; Determine if school is to remain K-12, a candidate for closure or to be combined as a K-8 with Mann
- If school is to remain open, consider a new site layout to provide safe student drop-off and walking access at school entrance, additional parking, and appropriate softscape and hardscape play area to meet curriculum needs
- Concepts should consider drop-off access to the school from 54th Street as well as a joint-campus plan with adjacent Horace Mann Middle School site
- New site layout should include solutions to site drainage problems, ADA
 compliant access throughout the site, site security lighting and a landscape
 barrier between commercial establishments on El Cajon Blvd. and classrooms
 buildings and play area







6: District Facilities Assessment

 At a minimum, replace buildings 01-01, 02-02, 03-04, and 04-04 with a multistory classroom building with quantity of classrooms to allow portables to be removed from site

Input from Site Survey:

• There will be a new charter in this location. A site survey will be filled out at a later date

Input From Cluster Meetings:

• No additional input received

