

6: District Facilities Assessment

Site Data Evaluation for Marshall Middle School

SITE DATA	MARSHALL MS	308
Site Net Acreage:	26	
Total Permanent Building Sq. Footage:	50,925	
Total Quantity of Classrooms:	59	
Quantity of Permanent Classrooms	59	
Number of Permanent Buildings	7	
School Program Capacity	1549	
Current Enrollment - 2007-08	1408	
Projected Enrollment - 2016-17:	1305	
Student to Acre Ratio:	54	
Quantity of Portable Classrooms	0	
% of Total Classrooms in Portables	0%	
Quantity of Portable Buildings on Site	0	
Quantity of Undersized Classrooms	0	
% of Undersized Classrooms	0%	
API Rating (2007 Base Statewide Rank)	10	
Quantity of buildings over 50 years	0	
Age of Building-% over 50 years	0%	
FCA Rating	Good	
Climate Control	III	
ADA Report	Good	
Delta from Capacity	141	

Site Findings:

- New proposition MM school
- There are no portables over 40 years old

Input from Site Survey:

- Natural turf needed for athletic field to accommodate sports programs
- Perimeter gates do not close and need to be upgraded to have self closers
- Access keys requested for administration building doors
- Lunch tables need to be fastened and skateboard deterrents needed to prohibit vandalism
- Some roofs reported as leaking and need to be repaired
- Some walls are open to vermin to enter and need to be repaired
- Additional campus-access road requested
- Expansion of bus loading area and turn-around needed to accommodate buses
- Additional parking spaces needed to accommodate staff
- Larger flag pole needed in order to fly U.S. and California flags
- New landscaping and irrigation requested in heavy traffic areas
- New signage needed for the library and parking/drop off areas
- Cabinetry and re-leveling of textbook room flooring requested
- Cabinets needed for the health office
- Boys' bathrooms need privacy walls so we can leave the doors open for safety/security reasons





6: District Facilities Assessment

Input from Cluster Meetings:

- Facilities need to be environmentally friendly. (solar panels, recycling)
- Toilets/bathrooms need upgrading
- Request flag pole
- Security issues reported
- PA system upgrade requested
- Continue to upgrade technology—more laptops, wireless access points
- Request site discretionary funds
- Request new bus loading zone
- Request new road leading to Marshall MS

