



6: District Facilities Assessment

Site Data Evaluation for Carver Elementary School

| SITE DATA | CARVER ES | 57 |
|--|-----------|----|
| Site Net Acreage: | 8.9 | |
| Total Permanent Building Sq. Footage: | 27,808 | |
| Total Quantity of Classrooms: | 33 | |
| Quantity of Permanent Classrooms | 14 | |
| Number of Permanent Buildings | 5 | |
| School Program Capacity | 646 | |
| Current Enrollment - 2007-08 | 380 | |
| Projected Enrollment - 2016-17: | 367 | |
| Student to Acre Ratio: | 43 | |
| Quantity of Portable Classrooms | 19 | |
| % of Total Classrooms in Portables | 58% | |
| Quantity of Portable Buildings on Site | 24 | |
| Quantity of Undersized Classrooms | 0 | |
| % of Undersized Classrooms | 0% | |
| API Rating (2007 Base Statewide Rank) | 1 | |
| Quantity of buildings over 50 years | 4 | |
| Age of Building-% over 50 years | 80% | |
| FCA Rating | Fair | |
| Climate Control | III | |
| ADA Report | Poor | |
| Delta from Capacity | 266 | |

Site Findings:

- The school is deficient 372 sq. ft. of administration & instructional support space to meet district standards
- There are 24 Portables not certified on site
- There are 2 separate schools operating on this one site
- The Arabic Immersion school is in 9 Portables
- 1 classroom is being used for a science room and 3 classrooms for support

Input From Site Surveys:

- Updated cabinetry requested in permanent building classrooms
- Repair or replacement of lunch tables requested
- Ramp to service driveway requested
- Unsafe student drop-off situation reported
- Portables exist without ADA compliant ramps
- Frequently non-functioning fire alarm system reported
- Carpet cleaning equipment requested

Input from Cluster Meetings:

- Request master clock with synchronized bells
- Need for irrigation reported
- PA system and telephone system upgrade
- Request AC with improved ventilation
- Request surveillance system
- Need to sustain and maintain all new installed systems (irrigation, vegetation,



6: District Facilities Assessment

tech, walkways, AC, ventilation, data)

- Request an area for special needs students with changing table for boys and girls
- Request snake prevention fence
- 6-8 rec/gym room or shade structure requested
- More trees requested
- Request that speed bumps be installed
- Request double pane, energy efficient glass
- Repair tripping hazards
- Request that school be painted

