

6: District Facilities Assessment

Site Data Evaluation for Horton Elementary School

SITE DATA	HORTON ES	149
Site Net Acreage:	8	
Total Permanent Building Sq. Footage:	42,868	
Total Quantity of Classrooms:	51	
Quantity of Permanent Classrooms	26	
Number of Permanent Buildings	4	
School Program Capacity	912	
Current Enrollment - 2007-08	578	
Projected Enrollment - 2016-17:	510	
Student to Acre Ratio:	72	
Quantity of Portable Classrooms	25	
% of Total Classrooms in Portables	49%	
Quantity of Portable Buildings on Site	27	
Quantity of Undersized Classrooms	0	
% of Undersized Classrooms	0%	
API Rating (2007 Base Statewide Rank)	2	
Quantity of buildings over 50 years	3	
Age of Building-% over 50 years	75%	
FCA Rating	Fair	
Climate Control	III	
ADA Report	Poor	
Delta from Capacity	334	

Site Findings:

- The school is deficient 864 sq. ft. of administration & instructional support space to meet district standards
- 24 portables are not certified; 17 portables are over 40 years old

Input from Site Survey:

- Wireless network needed campus-wide due to existing data/voice outlets not functioning, inadequately installed or not maintained
- New administration building needed to accommodate current staff and parents; Several offices are located outside of the administration building, causing privacy issues due to lack of space for principal & counselors
- New perimeter fencing, gates and security surveillance for safety
- Additional parking, student drop-off/bus-loading needed to accommodate staff/parents and community programs and frequent safety concerns
- Additional lighting campus-wide due to safety issues and vandalism
- Windows are reported non-functional
- Administration building electrical panel inadequate and reported to malfunction. Poor lighting reported in all buildings and classrooms
- Water line leak reported in parking causing damage to surface
- Restroom facilities, fixtures and finishes dilapidated and need repair
- Portables and buildings reported to be infested with termites and rodents due to cracks and holes
- Many facilities are not ADA accessible
- Fire and Security alarms are dysfunctional and cannot be heard campus-wide causing frequent safety and security concerns







6: District Facilities Assessment

Input from Cluster Meetings:

- Request whole school paint job
- Request shade structure on playground, larger lunch arbor
- Request joint-use turf field next to school
- Need larger multipurpose room with moveable walls reported

