



## **San Diego Unified School District – Construction Safety Audits**

<b>FACILITY</b>	Longfellow K-8, 5055 July St., San Diego, CA 92110
<b>PROJECT</b>	Whole Site Modernization
<b>CONTRACTOR CO.</b>	USS Cal Builders
<b>CONTRACTOR NAME</b>	Jesse Agustin
<b>SDUSD INSPECTOR</b>	Charlie Griffin
<b>ISPI INSPECTOR</b>	Bradley A. Prill, CIH, CSP

<b>POTENTIAL VIOLATIONS</b>	<b>Cal/OSHA, OSHA, GC* REFERENCE</b>	<b>COMMENTS / NOTES</b>
Electrical		
Fall Protection		
Fire Protection		
Housekeeping		
Ladders		
Laser Signage		
Rebar Caps		
Respiratory/PPE		
Scaffolding		
Site Security		
Tools/Equipment		
Trenching/Excavations		
Vehicle/Heavy Equipment	<b>Section 1597</b>	Worker operating skip loader was not wearing a seatbelt. See picture 1.
Other:		

\*The issues identified during the inspection are based on requirements associated with Cal/OSHA and OSHA regulations and/or contract specification requirements for the project to include SDUSD General Conditions.

### **Add'l Notes:**

- Site was secure at the time of the inspection.
- Workers were *not* following safety procedures at the time of the inspection. See notes above.
- Walked the site with Ronnie Anderson.

### **Safety Audit Photographs 06-27-2019 (pgs. 1-2)**



Pic 1.



Site Overview



Site Overview

**Safety Audit Photographs 06-27-2019 (cont.)**



Site Overview



Site Overview



Site Overview