Fax Number

Subcontractor's Pre-Job Conference Form: BAYVIEW ENVIRONMENTAL SERVICES, INC.

Status Published	Version 1		
Assigned PSA Specialist Maria Cruz	Email mcruz5@sandi.net	Phone Number (619) 879-7870	

Subcontractor's Information

Contractor

BAYVIEW ENVIRONMENTAL SERVICES, INC.

Company AddressPhone Number6925 SAN LEANDRO STREET OAKLAND, CA94621

CSLB License Number 684341 DIR Number 1000002423

Contractor License Classification

B - GENERAL BUILDING, C21 - BUILDING MOVING, DEMOLITION, C22 - ASBESTOS ABATEMENT (Check DOSH Asbestos Registration)

Pre-Award & Contract Information					
Bid Number CC22-0176-23A1-G1 & A1-G2	Bid Title Pacific Beach Elementary School Whole Site Modernization & Joint Use Field, GMP 1 & GMP	Prevaling Wage Determination 2023-1			
Contract Number CC22-0176-23A1-G1 & A1-G2	Contract Title Pacific Beach Elementary School Whole Site Modernization & Joint Use Field, GMP 1 & GMP	Contract Amount 22711331.00			

Overall Scope of Work for Which Your Company is Responsible

Overall Scope of Work

Abatement of floor tile and mastic, acoustic ceiling, lead containing plaster walls. Interior demolition of ceiling tiles, MEPs, walls, casework, and flooring.

Jobsite Scheduling Information			
Expected Start Date 6/26/2023	Estimated Duration(Days) 40		
Number of Shifts 1	Shift Description 7:00AM - 3:30AM		
Pay Day Friday	Pay Period End Day Friday		

Jobsite Administration				
JOBSITE CONTACT ? ADMISTRAT	IVE ROLE FIRST NAM	IE LAST NAME	EMAIL	PHONE
Yes Superintend	ent Jose	Torres	jtorres@bayviewservices.com	(562) 565-5847
Yes Foreman	Antonio	Galindo	agalindo@bayviewservices.co	m (562) 325-2263

Crew: Demolition

Scope of Work your firm will perform on this project Interior demolition of ceiling tiles, MEPs, walls, casework, and flooring. Equipment to be utilized in performing work on this Project Power tools and hand methods.

Referral and J	urisdictional Assi	gnment					
UNION	DIR CLASSIFICATION	ASSIGNMENT STATUS	CREW MEMBER ACTIVITIES/RESP ONSIBILITIES	SUMMARY OF WORK STATUS	ESTIMATED START - END DATE	ESTIMATED WORKFORCE AVERAGE	ESTIMATED WORKFORCE PEAK
Laborers Local 89	Laborer	Pending	Interior demolition.	Pending	6/26/2023 - 7/28/2023	10	10

Crew: Environmental

Scope of Work your firm will perform on this project Abatement of floor tile and mastic, acoustic ceiling, and lead containing plaster walls. Equipment to be utilized in performing work on this Project Power tools and hand methods.

Referral and Jurisdictional Assignment

UNION	DIR CLASSIFICATION	ASSIGNMENT STATUS	CREW MEMBER ACTIVITIES/RESP ONSIBILITIES	SUMMARY OF WORK STATUS	ESTIMATED START - END DATE	ESTIMATED WORKFORCE AVERAGE	ESTIMATED WORKFORCE PEAK
Laborers Local 300	Asbestos	Pending	Set up and abatement.	Pending	6/26/2023 - 8/18/2023	10	10

Add other direct Subcontractors not included on the Division of Work		
TBD?	TIERED SUBCONTRACTOR	TIERED SUBCONTRACTOR'S SCOPE
		Contractor not required to submit information